



Subject: OF4459/OF4459BP/WPH2808/WPH2808B Design Update

The OF4459/WPH2808 oil filter manufacturing location is changing from Greenville OH to Albion IL. There are no changes to fit or function, height, diameter, oil flow or internal valving. The primary change is in appearance, base plate and in the number of flutes. The current filter on right, has 15 flutes while the new filter on left has 14 flutes. Current design uses Service Champ cap wrench 3861 or A264, the new design will use Service Champ cap wrench 3862 or A251.

You will also notice a change in the outer case as the manufacturing facility change occurs. For a short period, inventory will be mixed on your shelves. Inventory rotation may help minimize this effect. We apologize for the inconvenience but filter demand requires a plant change.

Please contact your Service Champ representative with further questions.



New Design

Current Design

For more information or purchase, please call Technical Services at 1-800-882-0890. Champion Laboratories is an ISO/TS16949 registered company. The information contained herein is intended to be used as an indication of performance and is not meant to be used as an exact specification. The information is based upon test data and is subject to test and material variability. Changes may occur based upon technology, process and material innovation as Champion Laboratories strives to attain the highest levels of performance and customer satisfaction. These changes may occur without notification.

Engine and equipment manufacturer's warranties remain in effect when using Champ filters