



Technical Bulletin Date: 03.19.2019 TSB: 19.03.19.01

New Replacement Oil Filter for GM Applications WPH1500 / WPH1500BP certain General Motors 3.0 & 3.6L V6 engines Ref GM TSB 19-NA-020 Replacing OF2222/WPH48

GM High Feature V6 engines RPO (LGX) and (LGW) have higher oil pump pressure to accommodate engine cam phasing and high-speed bearing requirements. As a result, the oil filter performance was improved to meet this higher oil pressure output.

The new WPH1500 oil filter has a thicker outer shell to provide higher burst pressure resistance during cold temperature conditions and greater fatigue strength. Failing to use this filter could result in external oil leaks due to gasket blowout or wrench flute cracks.

It is recommended on future installations to use the new and improved filter. Previous installation of OF2222 is still covered by our warranty and there is no need to replace the previously recommended, installed filters.

Brand	Model	Model Year:		Engine	Transmission
		From	to		
Buick	Lacrosse	2017	2019		All
Buick	Regal	2018	2019		All
Cadillac	ATS, CT6,	2016	2019		All
	CTS			3.6 & 3.0L V6	
Cadillac	XT5	2017	2019	LGX & LGW	All
Chevrolet	Camaro	2016	2019		All
Chevrolet	Blazer	2019	2019		All
GMC	Acadia	2017	2019		All

Engine and equipment manufacturer's warranties remain in effect when using Service Champ filters

For more information or purchase, please call Technical Services at 1-800-882-0890 Champion Laboratories is an ISO/TS16949 registered company. The information contained herein is intended to be used as an indication of performance and is not meant to be used as an exact specification. The information is based upon test data and is subject to test and material variability. Changes may occur based upon technology, process and material innovation as Champion Laboratories strives to attain the highest levels of performance and customer satisfaction. These changes may occur without notification.